

ECS operational staff meeting household appliances decision sheet			OSM HA N°295
Sub cl.	Meeting	Agenda item	Document
24.5	15	10.8	(IT)03/01
Standard	EN 60335-2-17:1999 EN 60335-2-17:2013	Date	2017-02-08
Question	Is the construction of a blanket provided with a 4 poles appliance inlet (special connector), where is possible to replace this special connector with a 2 poles connector complying with EN 60320, acceptable?		
Decision	This construction is acceptable if the blanket can operate with a standardised (harmonized) 2 pole - connector (EN 60320) and the requirements for double insulation are respected and clauses 11 and 19 are repeated with positive results. If the blanket can not operate, only basic insulation is needed.		
Explanatory notes			